# RSFlite Public Manifest

November 25, 2022

## 2022-11-26 RSFlite 4.5.3

### New Features

**4619** Correct HV error message to reduce confusion

**4600** Improve HV error management

**4634** Change in UT Filters specification

## 2022-03-17 RSFlite 4.5.2

### New Features

None, follows other products' software version ID.

### Known Issues

**4547** The touchscreen may stop working when a VNC session has been closed.

## 2021-10-22 RSFlite 4.5.1

### New Features

None, follows other products' software version ID.

### Known Issues

**4547** The touchscreen may stop working when a VNC session has been closed.

## 2021-10-12 RSFlite 4.5.0

### New Features

**4461** New X6BW flat .utwedge files.

**4471** New StarTech WiFi dongle support.

**4535** There are new X2B probes and wedges.

### Fixed Issues

**4208** The RSflite could crash when the user clicks the "Next Index" software button.

**4364** The part overlay "W" shortcut is fixed.

**4366** Focus goes to the menus once you loaded a probe or a wedge.

## Known Issues

**4547** The touchscreen may stop working when a VNC session has been closed.

# 2021-04-07 RSFlite 4.4.0

## New Features

**4115** New touchscreen and keypad

**4144** Improved Touchscreen Response

**4308** New Xpair update

## Fixed Issues

**3687** New probe in UTstudio+ have all elements activated by default

**3694** TCG is not reset when the start path is moved beyond the first point

**3717** TCG curve interpolation improvement when a TCG point is outside of the scan

**4223** Pulse width value of the MSEB4 probe has been updated.

# 2020-09-01 RSFlite 4.3.0

## New Features

**3790** Chinese language have been improve for RSflite

**3804** RSflite can now generate Merge C-Scan

**3926** Touchscreen Sensitivity to change the colour palette has been improved

**3930** The welcome screen has been refurbished and is now offering the User's Template concept.

**3933** New layout with B-scan have been added

**4092** For conventional UT configuration the T-loss functionality is now available for DAC/TCG calibration

## Fixed Issues

**3701** Layout A-L-C Amp-C Depth is now showing the proper view

# 2020-01-24 RSFlite 4.2.6

## New Features

None, follows other products' software version ID.

## Known Issues

**3638** Alphabetic Keypad in lieu of Numeric Keypad for some parameters

# 2019-06-21 RSFlite 4.2.4

## New Features

None

## Fixed Issues

**3706** Internal tools enhancement

### Known Issues

**3638** Alphabetic Keypad in lieu of Numeric Keypad for some parameters

## 2019-03-28 RSFlite 4.2.3

### New Features

 None

### Fixed Issues

**3692** Internal tools enhancement

### Known Issues

**3638** Alphabetic Keypad in lieu of Numeric Keypad for some parameters

## 2019-03-12 RSFlite 4.2.2

### New Features

None, follows other products' software version ID.

### Known Issues

**3638** Alphabetic Keypad in lieu of Numeric Keypad for some parameters

## 2018-11-22 RSFlite 4.2.1

### New Features

**3494** Translation file for French, Chinese, Slovak, Czech, Russian

## 2018-10-17 RSFlite 4.2.0

### New Features

None, follows other products' software version ID.