VEO+ Public Manifest

VEO+ 3.10

Important Application Notice

None

2016-04-21 VEO+ Release 3.10.10

Improvements

1476 Update for multiple OS security fixes.
1584 New layout for 5 Scan that includes a B-Scan.

Fix 1397 Mono DAC interface.
Fix 1490 UT function noise.

Known Issues

32 File loaded from USB key cannot be saved after removing the key.
40 Maximizing Merged C-scan view clears the view.
90 Error in FL calculation - Beam exit point outside wedge.
565 3D views improvement for P&C functionalities.
609 Screen brightness parameter missing.
635 WiFi refresh button in configuration screen not working. - WA turn OFF/ON the antenna.
601 WiFi right password isn't recognize correctly after reboot - WA re-enter password.
592 Auto FSH in DGS wizard not accurate - WA make manual adjustment.
363 Wheel touch doesn't work while in velocity wizard - WA use arrows.
322 F3 reset shortcut doesn't work when 2D quadrature encoded - WA manual reset.
280 Measures in Part References don't consider Encoding Area offset+rotation.
263 Reset all in Time-based should reset all data - WA manual reset.
236 Sometimes split DAC vertical lines are not drawn.
231 Redundant info in 3D view or wrong abbreviation used for focal distance.
1439 AQR indicator unespected behavior when having 2 TOFD scans.
1541 Part Thickness and geometry index offset breaks calibration

2016-03-15 VEO+ Release 3.10.8

Improvements

First public release.