2026-01-20 - v2.1.2

Fixed Issues

- 5294 - Resolved issues with point deletion during JIS DAC curve calibration.