# **RSFlite** Public Manifest

January 17, 2023

## 2023-01-17 RSFlite 4.5.4

#### **New Features**

4680 Improve HV error management

#### **Fixed Issues**

 ${\bf 4684} \ {\rm Fix} \ {\rm missing} \ {\rm translations}$ 

## 2022-11-26 RSFlite 4.5.3

#### **New Features**

4619 Correct HV error message to reduce confusion4600 Improve HV error management4634 Change in UT Filters specification

## 2022-03-17 RSFlite 4.5.2

#### **New Features**

None, follows other products' software version ID.

#### Known Issues

4547 The touchscreen may stop working when a VNC session has been closed.

## 2021-10-22 RSFlite 4.5.1

#### **New Features**

None, follows other products' software version ID.

#### Known Issues

4547 The touchscreen may stop working when a VNC session has been closed.

## 2021-10-12 RSFlite 4.5.0

#### **New Features**

 ${\bf 4461}\,$  New X6BW flat .utwedge files.

- ${\bf 4471}\,$  New StarTech WiFi dongle support.
- 4535 There are new X2B probes and wedges.

#### **Fixed Issues**

4208 The RSflite could crash when the user clicks the "Next Index" software button.

4364 The part overlay "W" shortcut is fixed.

4366 Focus goes to the menus once you loaded a probe or a wedge.

#### Known Issues

4547 The touchscreen may stop working when a VNC session has been closed.

# 2021-04-07 RSFlite 4.4.0

#### **New Features**

4115 New touchscreen and keypad

4144 Improved Touchscreen Response

 $4308 \ {\rm New \ Xpair \ update}$ 

#### **Fixed Issues**

3687 New probe in UTstudio+ have all elements activated by default

3694 TCG is not reset when the start path is moved beyond the first point

3717 TCG curve interpolation improvement when a TCG point is outside of the scan

4223 Pulse width value of the MSEB4 probe has been updated.

## 2020-09-01 RSFlite 4.3.0

#### **New Features**

3790 Chinese language have been improve for RSflite

- **3804** RSflite can now generate Merge C-Scan
- 3926 Touchscreen Sensitivity to change the colour palette has been improved
- 3930 The welcome screen has been refurbished and is now offering the User's Template concept.
- $\mathbf{3933}$  New layout with B-scan have been added
- 4092 For conventional UT configuration the T-loss functionality is now available for DAC/TCG calibration

#### **Fixed Issues**

3701 Layout A-L-C Amp-C Depth is now showing the proper view

## 2020-01-24 RSFlite 4.2.6

#### New Features

None, follows other products' software version ID.

#### Known Issues

3638 Alphabetic Keypad in lieu of Numeric Keypad for some parameters

# 2019-06-21 RSFlite 4.2.4

### **New Features**

None

Fixed Issues

**3706** Internal tools enhancement

## Known Issues

3638 Alphabetic Keypad in lieu of Numeric Keypad for some parameters

# 2019-03-28 RSFlite 4.2.3

**New Features** 

None

Fixed Issues 3692 Internal tools enhancement

## Known Issues

3638 Alphabetic Keypad in lieu of Numeric Keypad for some parameters

# 2019-03-12 RSFlite 4.2.2

## **New Features**

None, follows other products' software version ID.

## Known Issues

 $\mathbf{3638}$  Alphabetic Keypad in lieu of Numeric Keypad for some parameters

# 2018-11-22 RSFlite 4.2.1

## **New Features**

3494 Translation file for French, Chinese, Slovak, Czech, Russian

# 2018-10-17 RSFlite 4.2.0

### New Features

None, follows other products' software version ID.