RSFlite Public Manifest

April 7, 2021

2021-04-07 RSFlite 4.4.0

New Features

- 4115 New touchscreen and keypad
- 4144 Improved Touchscreen Response
- 4308 New Xpair update

Fixed Issues

- 3687 New probe in UTstudio+ have all elements activated by default
- 3694 TCG is not reset when the start path is moved beyond the first point
- 3717 TCG curve interpolation improvement when a TCG point is outside of the scan
- 4223 Pulse width value of the MSEB4 probe has been updated.

2020-09-01 RSFlite 4.3.0

New Features

- 3790 Chinese language have been improve for RSflite
- 3804 RSflite can now generate Merge C-Scan
- 3926 Touchscreen Sensitivity to change the colour palette has been improved
- 3930 The welcome screen has been refurbished and is now offering the User's Template concept.
- 3933 New layout with B-scan have been added
- 4092 For conventional UT configuration the T-loss functionality is now available for DAC/TCG calibration

Fixed Issues

3701 Layout A-L-C Amp-C Depth is now showing the proper view

2020-01-24 RSFlite 4.2.6

New Features

None, follows other products' software version ID.

Known Issues

3638 Alphabetic Keypad in lieu of Numeric Keypad for some parameters

2019-06-21 RSFlite 4.2.4

New Features

None

Fixed Issues

3706 Internal tools enhancement

Known Issues

3638 Alphabetic Keypad in lieu of Numeric Keypad for some parameters

2019-03-28 RSFlite 4.2.3

New Features

None

Fixed Issues

3692 Internal tools enhancement

Known Issues

3638 Alphabetic Keypad in lieu of Numeric Keypad for some parameters

2019-03-12 RSFlite 4.2.2

New Features

None, follows other products' software version ID.

Known Issues

3638 Alphabetic Keypad in lieu of Numeric Keypad for some parameters

2018-11-22 RSFlite 4.2.1

New Features

3494 Translation file for French, Chinese, Slovak, Czech, Russian

2018-10-17 RSFlite 4.2.0

New Features

None, follows other products' software version ID.